



# IECEX CoC Certified Service Facility

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

Certificate No.: **IECEX NCC S0002** Page 1 of 1 [Certificate history:](#)  
Issue 0 (2019-12-17)

Date of Issue: 2019-12-17 Issue No: 0

Applicant: **Alcon Engenharia de Sistemas Ltda.**  
Paulo Orozimbo, 1190 - Cambuci  
São Paulo/SP 01535-001  
**Brazil**

Type of Service: **Repair and Overhaul according to IEC 60079-19**

Type of Protection: **03-5 Program - Repair Overhaul and Reclamation  
Intrinsic Safety "i"**

Scope of Service: Maintenance, repair and overhaul of intrinsically safe type communication radios for use in Explosive Atmospheres.

Locations covered by this Certificate:

**Alcon Engenharia de Sistemas Ltda.**  
Paulo Orozimbo, 1190 - Cambuci  
São Paulo/SP 01535-001  
**Brazil**

Facility Audit Report:

[BR/NCC/FAR19.0001/00](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx  
Certification Body:

**Wilson Bonato**

Position:

**Technical Manager**

Signature:  
(for printed version)

Date:

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting [www.iecex.com](http://www.iecex.com) or use of this QR Code.



Certificate issued by:

**NCC Certificações do Brasil Ltda**  
**Rua Conceição 233, Suite 2511**  
**ZIP 13010-916, Campinas, SP**  
**Brazil**

